



Add oil seals on the motor flange only for ATEX or double input seal

ATBA030*047*07C for PAM63-71-80; NEMA56
ATBA035*047*07C for PAM90; NEMA143/5

Code	IEC	**Motor fixing screws
063.4.041	63 B5	n°4 M8x30 T.E.
063.4.042	71 B5	n°4 M8x30 T.E.
063.4.043	80 B5	n°4 M10x35 T.E.
063.4.043	90 B5	n°4 M10x35 T.E.
063.4.047	71 B14	n°3 M6x20 T.E.
063.4.046	80 B14	n°3 M6x20 T.E.
063.4.041	90 B14	n°4 M8x20 T.E.
U0634041	56C/143/5	-

* (Please Ask) Depending on the ratio

Order from parts required from gearbox size FA53 ratio
From: _____ Date: ____/____/____

Parts	Q.ty	Description