



No mount for mounting position B8  
→ First gear  
→ First gear

Only for mounting position V5  
For all positions except V5

No mount for mounting position B8  
→ First gear  
→ First gear

Only for mounting position V5  
For all positions except V5

Code	IEC	**Motor fixing screws
050.4.041	63 B5	n°4 M8x30 T.E.
050.4.042	71 B5	n°4 M8x30 T.E.
050.4.047	63 B14	n°3 M5x16 T.C.E.I.
050.4.045	71 B14	n°4 M6x20 T.E.

Code	IEC	**Motor fixing screws
063.4.041	63 B5	n°4 M8x30 T.E.
063.4.042	71 B5	n°4 M8x30 T.E.
063.4.043	80 B5	n°4 M10x35 T.E.
063.4.043	90 B5	n°4 M10x35 T.E.
063.4.047	71 B14	n°3 M6x20 T.E.
063.4.046	80 B14	n°3 M8x20 T.E.
063.4.041	90 B14	n°4 M8x20 T.E.

\* (Please Ask) Depending on the ratio

Order from parts required from gearbox size P6A ratio

From \_\_\_\_\_ Date \_\_\_\_/\_\_\_\_/\_\_\_\_

Parts	Q.ty	Description