



Code	Mot.	**Motor fixing screws
C0234041	71 B5	n°4 M8x30 T.E.
C0234042	80/90 B5	n°4 M10x35 T.E.
C0234043	100/112 B5	n°4 M12x45 T.E.
C0854046	80 B14	n°4 M6x20 T.E.
C0854045	90 B14	n°4 M8x20 T.E.
C0854047	100/112 B14	n°4 M8x20 T.E.
U0854041	56C-143/5	-
U0854042	182/4TC	-
UC504041	213/5TC	-

ATBA035\*062\*07C for PAM 71-80  
NEMA 56C-143/5  
ATBA040\*062\*07C for PAM 90-100/112  
ATBA045\*062\*07C for NEMA 182/4

Add oil seals on the motor flange only for ATEX or double input seal

\* (Please Ask) Depending on the ratio

Order from parts required from gearbox size X52A ratio \_\_\_\_\_

From \_\_\_\_\_ Date \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

Parts	Q.ty	Description