



Code	IEC	**Motor fixing screws
063.4.041	63 B5	n°4 M8x30 T.E.
063.4.042	71 B5	n°4 M8x30 T.E.
063.4.043	80 B5	n°4 M10x35 T.E.
063.4.043	90 B5	n°4 M10x35 T.E.
063.4.047	71 B14	n°3 M6x20 T.E.
063.4.046	80 B14	n°3 M6x20 T.E.
063.4.041	90 B14	n°4 M8x20 T.E.
U06.34041	56C-143/5	-

* (Please Ask) Depending on the ratio

Order from parts required from gearbox size 114C ratio

From: _____ Date: ____/____/____

Parts	Qty	Description

Fax: +39 0444 536139 ---- e-mail: hydromec@hydromec.com

ATBA030*047*07C
for PAM63-71-80; NEMA56
ATBA035*047*07C
for PAM90; NEMA143/5

Add oil seals on the
motor flange only for ATEX
or double input seal